

Alterations Notices Issued by GFRS under the Regulatory Reform (Fire Safety) Order 2005

Premise Ref	Alt Notice Ref No	Date Served	Premise Name & Address	Matters specified remedied? (Date)	Reason for Notice
00046240	320	05 Jun 2023	MB Electrical 174 Southgate Street Gloucester GL1 2EZ	In Force	<p>Inadequate levels of fire resisting compartmentation between the commercial side and the residential side of the premises. The means of escape from the residential side of the premises is not a protected route to a place of ultimate safety.</p> <p>You must notify this authority before you: Allow any persons to use any part of the premises for residential or sleeping purposes.</p>

Premise Ref	Alt Notice Ref No	Date Served	Premise Name & Address	Matters specified remedied? (Date)	Reason for Notice
00017560	319	12 Apr 2023	T-Level Building Cirencester College Stroud road Cirencester GL7 1XA	In Force	<p>The fire engineering within the building may not work as intended if the fire-loading at the base of the atrium is not controlled. Combustible materials must not exceed the level as indicated within the fire strategy provided to this authority during the design consultation. Combustible materials and ignition sources must be kept within this modelling to ensure that the smoke extraction system can cope with the volume of smoke for long enough to allow all relevant persons time to safely evacuate.</p>

Premise Ref	Alt Notice Ref No	Date Served	Premise Name & Address	Matters specified remedied? (Date)	Reason for Notice

00017560	317	03 Nov 2022	Digital Building Cirencester College Stroud road Cirencester GL7 1XA	In Force	The fire engineering within the building may not work as intended if the fire-loading at the base of the atrium is not kept as low as reasonably practicable. Combustible materials must not exceed the level as indicated within the fire strategy provided to this authority during the design consultation. Combustible materials and ignition sources must be kept as low as possible to ensure that the smoke extraction system can cope with the volume of smoke for long enough to allow all relevant persons time to safely evacuate.
----------	-----	-------------	---	-----------------	---

Premise Ref	Alt Notice Ref No	Date Served	Premise Name & Address	Matters specified remedied? (Date)	Reason for Notice
00000811	246	02 Nov 2015	Honeybourne Gate 2 Gloucester Road Cheltenham Glos. GL51 8PE	In Force	No fire protection being afforded to front fascia of the flats which opens onto the atria, therefore all requirements in the fire design strategy should be adhered to.

Premise Ref	Alt Notice Ref No	Date Served	Premise Name & Address	Matters specified remedied? (Date)	Reason for Notice

00033654	97	25 Mar 2011	Staff Accommodation 18 Gloucester Street Stroud Glos. GL5 1QG	In Force	Omission of a protected escape route from the sleeping accommodation leading directly to a final exit and suitable fire detection within the premises.
----------	----	-------------	--	-----------------	--