

**Prohibition Notices Issued by GFRS under the Regulatory Reform (Fire Safety) Order 2005**

| Premise Ref               | Prohib Notice Ref No. | Date Served  | Premise Name & Address  | Matters specified remedied? (Date) |
|---------------------------|-----------------------|--|---|------------------------------------|
| 00016459                  | PN216                 | 04 Sep 2023  | <b>Harbour City Takeaway</b><br>42 Edinburgh Place<br>Coronation Square<br>Cheltenham<br>GL51 7SA | <b>No - In Force</b>               |
| <b>Reason for Notice:</b> |                       | <ul style="list-style-type: none"><li>Inadequate fire detection and no protected means of escape from the first floor to place of ultimate safety, which would put person(s) at serious risk to the effects of a fire.</li></ul> |   |                                    |

| Premise Ref               | Prohib Notice Ref No. | Date Served  | Premise Name & Address  | Matters specified remedied? (Date)                 |
|---------------------------|-----------------------|--|---|--|
| 00028477                  | PN215                 | 14 Oct 2022  | <b>Regency Hall</b><br>Fishers Lane<br>Cheltenham<br>GL52 2NY | Yes –<br>Prohibition Notice Lifted<br>(27/02/2023) |
| <b>Reason for Notice:</b> |                       | <ul style="list-style-type: none"><li>Lack of suitable fire detection and alarm system</li></ul> |   |  |

| Premise Ref               | Prohib Notice Ref No. | Date Served   | Premise Name & Address  | Matters specified remedied? (Date) |
|---------------------------|-----------------------|---|---|------------------------------------|
| 00016340                  | PN214                 | 13 Jul 2022   | <b>Cheltenham Star Nails</b><br>273 High Street<br>Cheltenham<br>GL50 3HL | <b>No - In Force</b>               |
| <b>Reason for Notice:</b> |                       | <ul style="list-style-type: none"> <li>• Lack of protected escape route</li> <li>• Lack of suitable detection and warning throughout</li> </ul> |   |                                    |

| Premise Ref               | Prohib Notice Ref No. | Date Served   | Premise Name & Address  | Matters specified remedied? (Date)                 |
|---------------------------|-----------------------|---|---|--|
| 00024201                  | PN213                 | 29 Oct 2021   | <b>Dragonfly Takeaway</b><br>86 London Road<br>Cheltenham<br>GL52 6EH | Yes –<br>Prohibition Notice Lifted<br>(03/01/2023) |
| <b>Reason for Notice:</b> |                       | <ul style="list-style-type: none"> <li>• Lack of warning in the event of fire</li> <li>• No protected means of escape from the first floor accommodation</li> <li>• Lack of structural fire protection and fire separation</li> </ul> |   |  |

| Premise Ref               | Prohib Notice Ref No. | Date Served   | Premise Name & Address  | Matters specified remedied? (Date) |
|---------------------------|-----------------------|---|---|------------------------------------|
| 00002236                  | PN210                 | 08 Nov 2019   | <b>Spreadeagle Court</b><br>106-110 Northgate Street<br>Gloucester<br>GL1 1SL | <b>No - In Force</b>               |
| <b>Reason for Notice:</b> |                       | <ul style="list-style-type: none"> <li>No fire warning throughout premises</li> <li>Excess travel distances due to blocked escape routes</li> </ul> |   |                                    |

| Premise Ref               | Prohib Notice Ref No. | Date Served  | Premise Name & Address   | Matters specified remedied? (Date)              |
|---------------------------|-----------------------|--|--|---|
| 00010272                  | PN208                 | 08 Feb 2019  | <b>Kebab &amp; Pizza House</b><br>57 Parsonage Street<br>Dursley<br>GL11 4BP | Yes –<br>Prohibition Notice Lifted (26/09/2019) |
| <b>Reason for Notice:</b> |                       | <ul style="list-style-type: none"> <li>No Fire Detection</li> <li>No Emergency Lighting</li> <li>No Protected Route</li> </ul> |  |   |

| Premise Ref               | Prohib Notice Ref No. | Date Served   | Premise Name & Address                                       | Matters specified remedied? (Date)              |
|---------------------------|-----------------------|---|--|---|
| 00010681                  | PN207                 | 12 Oct 2018   | <b>Wokswagon</b><br>77 Priors Road<br>Cheltenham<br>GL52 5AL | Yes –<br>Prohibition Notice Lifted (18/12/2018) |
| <b>Reason for Notice:</b> |                       | <ul style="list-style-type: none"> <li>• The means of escape from the inner room is through a high risk commercial kitchen</li> <li>• No fire detection</li> <li>• No fire warning</li> <li>• No window escape available</li> </ul> |  |   |

| Premise Ref               | Prohib Notice Ref No. | Date Served   | Premise Name & Address   | Matters specified remedied? (Date) |
|---------------------------|-----------------------|---|--|------------------------------------|
| 00040858                  | PN201                 | 17 Jan 2017   | <b>The Convent</b><br>Convent Lane<br>South Woodchester<br>Stroud<br>GL5 5HS | <b>No - In Force</b>               |
| <b>Reason for Notice:</b> |                       | <ul style="list-style-type: none"> <li>• There is insufficient fire resisting separation between the bedrooms and the means of escape from the upper floors. Any fire in a bedroom will result in heat and/or smoke filling the escape route and prevent people in the bedrooms from making a safe escape from the premises.</li> </ul> |  |                                    |

| Premise Ref               | Prohib Notice Ref No. | Date Served   | Premise Name & Address  | Matters specified remedied? (Date) |
|---------------------------|-----------------------|---|---|------------------------------------|
| 00013231                  | PN200                 | 13 Dec 2016   | <b>Emperor Chinese Takeaway</b><br>Unit 7 Olympus Park<br>Quedgeley District centre<br>Quedgeley<br>Gloucester<br>GL2 4NF | <b>No - In Force</b>               |
| <b>Reason for Notice:</b> |                       | <ul style="list-style-type: none"> <li>• There is insufficient fire and smoke protection between the Kitchen and upper floor.</li> <li>• This will allow heat and smoke from a fire to pass from the area of the fire to upper floor.</li> <li>• Due to insufficient fire detection and warning, people sleeping on the upper floor would be unaware of the fire and would be likely to be overcome by the effects of heat and/or smoke before they could make their escape.</li> </ul> |   |                                    |

| Premise Ref               | Prohib Notice Ref No. | Date Served   | Premise Name & Address  | Matters specified remedied? (Date)                 |
|---------------------------|-----------------------|---|---|--|
| 00044735                  | PN199                 | 13 Dec 2016   | <b>East &amp; West Foods</b><br>449-451 High Street<br>Cheltenham<br>GL50 3HX | Yes -<br>Prohibition Notice Lifted<br>(18/08/2023) |
| <b>Reason for Notice:</b> |                       | <ul style="list-style-type: none"> <li>• No protected escape route</li> <li>• No fire separation between floors</li> <li>• Means of escape through a high risk area (kitchen)</li> <li>• No fire alarm system</li> <li>• No emergency lighting</li> <li>• Means of escape obstructed</li> <li>• Bedrooms are inner rooms</li> <li>• Key lockable rooms</li> </ul> |   |  |

| Premise Ref               | Prohib Notice Ref No. | Date Served  | Premise Name & Address   | Matters specified remedied? (Date) |
|---------------------------|-----------------------|--|--|------------------------------------|
| 00001291                  | PN192                 | 08 Mar 2016  | <b>Eastgate Off Licence/Flat</b><br>138 Eastgate Street<br>Gloucester<br>GL1 1QU | <b>No - In Force</b>               |
| <b>Reason for Notice:</b> |                       | <ul style="list-style-type: none"> <li>• Lack of fire alarm system between commercial premises and first floor domestic premises</li> <li>• Lack of fire separation between commercial premises and first floor domestic premises</li> <li>• Inadequate means of escape</li> </ul> |  |                                    |

| Premise Ref               | Prohib Notice Ref No. | Date Served  | Premise Name & Address  | Matters specified remedied? (Date)              |
|---------------------------|-----------------------|--|---|---|
| 00013992                  | PN188                 | 05 Feb 2015  | <b>Robis Takeaway</b><br>240 Bath Road<br>Cheltenham<br>Glos.<br>GL53 7NB | Yes - Prohibition Notice Lifted<br>(18/08/2023) |
| <b>Reason for Notice:</b> |                       | <ul style="list-style-type: none"> <li>• Inadequate means of escape from the first room on the left hand side on the first floor, currently a storage room, as there is not a protected route that offers 30 minutes fire protection and does not allow occupants safe egress from this room in a fire situation. Window escape is not a viable option.</li> </ul> |   |   |

| Premise Ref               | Prohib Notice Ref No. | Date Served   | Premise Name & Address  | Matters specified remedied? (Date) |
|---------------------------|-----------------------|---|---|------------------------------------|
| 00007664                  | PN178                 | 26 Sep 2012   | <b>Shisha Bar</b><br>Amaras Kitchen<br>72 Bristol Road<br>Gloucester<br>GL1 5SD | <b>No - In Force</b>               |
| <b>Reason for Notice:</b> |                       | <ul style="list-style-type: none"> <li>• Excess travel distance to a place of safety.</li> <li>• Inadequate construction and fire resistance.</li> <li>• Inadequate emergency lighting.</li> <li>• Inadequate means of escape.</li> </ul> |   |                                    |